

## *C W Harrison & Son Catalogue 24 Apr 2023*

- |   |  |
|---|--|
| <p>1 HONDA JAZZ ES+ I-VEC 1.3 FIVE DOOR HATCHBACK - Petrol - Grey.<br/>On the instructions of: A firm of solicitors dealing with a deceased estate.<br/>Registration No: YG64 KZZ.<br/>Recorded Mileage: 26,956+.<br/>First Registered: 15-09-2014.<br/>Documents: No documents.<br/>MOT: Expired 14-09-2022, mileage as at 14-09-2022 was 26,335+.<br/>Service History: Yes and booklet. Delivery stamp and seven others from 08-09-2015, 4,850 to 14-09-2021 at 26,3389.<br/>Number of Former Keepers: None.<br/>Keys: One.<br/>Runner: Yes.<br/>Condition/Damages: Scrapes to front bumper, scratches to front wing, passenger side front door and bonnet, rust marks on tailgate.</p> <p>2 MERCEDES BENZ E280 CDI AVANTGARDE AUTOMATIC SALOON - Diesel - Black - Beige leather interior.<br/>Noted on VCAR as a Category N Insurance Loss - No structural damage and repairable, insurer decided not to repair 06-05-2022.<br/>On the instructions of: A High Court Enforcement Office,<br/>Registration No: MV08 FON.<br/>Recorded Mileage: 147,057+.<br/>First Registered: 18-03-2008.<br/>Documents: Yes, but no section 6, new keeper slip.<br/>MOT: Expired 28-10-2022.<br/>Service History: No service history or handbook.<br/>Number of Former Keepers: 5<br/>Keys: One.<br/>Runner: Yes.<br/>Condition/Damages: Alloy wheels. No spare wheel. Damage to passenger side front door. Air con.</p> <p>3 FORD KA COLLECTION 1.3 THREE DOOR HATCHBACK - Petrol - Black.<br/>On the instructions of: A firm of solicitors dealing with a deceased estate.<br/>Registration No: YK02 ZBU.<br/>Recorded Mileage: 25,043+<br/>First Registered: 25-03-2002.<br/>Documents: No documents.<br/>MOT: 27-03-2023, mileage at last MOT on 22-03-2022 was 24,557. MOT history would suggest mileage is correct.<br/>Service History: No.<br/>Number of Former Keepers: One.<br/>Keys: One.<br/>Runner: Yes.<br/>Condition/Damages: Scrapes to front and rear bumper and driver's door mirror, scratches to panels on driver's side and tailgate, passenger side panels and bonnet,</p> <p>4 RENAULT LAGUNA 2.0 RT ESTATE - Petrol - Silver.<br/>On the instructions of: A firm of solicitors dealing with a deceased estate.<br/>Registration No: N407 EWF.</p> | <p>Recorded Mileage: 74,764+.<br/>First Registered: 28-03-1996.<br/>Documents: Yes.<br/>MOT: Expired 21-03-2022, mileage as at 22-02-2021 was 75,869+.<br/>Service History: No.<br/>Number of Former Keepers: None.<br/>Keys: Two.<br/>Runner: Yes.<br/>Condition/Damages: The condition of the vehicle is very good.</p> <p>*5 VW TRANSPORTER T28 84 1.9 tdi SWB PANEL VAN - Diesel - White.<br/>On the instructions of: A firm of liquidators re Midland Rubber Co. Ltd. in liquidation.<br/>Registration No: YE07 LLR.<br/>Recorded Mileage: 34,216+.<br/>First Registered: 15-05-2007.<br/>Documents: Yes.<br/>MOT: 14-10-2023. The MOT history suggests the mileage is correct.<br/>Service History: Yes.<br/>Number of Former Keepers: None.<br/>Keys: Two.<br/>Runner: Yes.<br/>Condition/Damages: Cracked rear light lens passenger side, scratches to rear panel and door hinge on driver's side.</p> <p>6 MTD LAWNFLITE 603 RIDE ON LAWNMOWER with Briggs &amp; Stratton 12.5 petrol engine, complete with collection bucket.<br/>No keys, sold as viewed (Saleroom location: MWDT)</p> <p>7 Contents to pallet - fifteen pieces of York stone paving, sizes approximately 80cm x 60cm, 75cm x 75, smallest 53cm x 30cm (Saleroom location: OS)</p> <p>8 Contents to pallet - eleven pieces of York stone paving - sizes approximately 91cm x 63cm, 60cm x 50cm, smallest 38cm x 62cm (Saleroom location: OS)</p> <p>9 A vintage A C Morrison 7.5KWA petrol generator with a Ford 100E engine and a Stamford alternator, 135cm x 70cm x 110cm high (Saleroom location: SMA)</p> <p>10 VOLVO V70 24D ESTATE AUTOMATIC - Diesel - Red - Cream leather interior.<br/>On the instructions of: A retained client.<br/>Registration No: OE55 GMX.<br/>Recorded Mileage: 170,576+.<br/>First Registered: 22-12-2005<br/>Documents: Yes (no V5/C3 trader supplement)<br/>MOT: Expired 30-03-2023.<br/>Service History: No.<br/>Number of Former Keepers: 4.<br/>Keys: Two.<br/>Runner: Yes.<br/>Condition/Damages: Dents to front wing driver's side, driver's door and rear door, light scratches to driver's side panel, dents to front wing on passenger side, light scratches to passenger side panels and bonnet.</p> |
|---|--|

- \*11 FORD TRANSIT 96 2.2 T300M FWD PANEL VAN -  
 Diesel - White  
 On the instructions of: The Official Receivers  
 Office re a Company Liquidation.  
 Registration No: YR07 FPN.  
 Recorded Mileage: 203,291+.  
 First Registered: 19-03-2007.  
 Documents: Yes.  
 MOT: 07-07-2023.  
 Service History: No.  
 Number of Former Keepers: THree.  
 Keys: One.  
 Runner: Yes.  
 Condition/Damages: The interior of the vehicle is  
 very rough. Scratches to all panels and rear  
 doors. Damage to side and rear panel driver's  
 side, scratches dents and damage to side door,  
 rear panel passenger side and passenger door.  
 Passenger side door mirror broken. Cracked  
 windscreen.
- 12 \*\*\* Lot Withdrawn \*\*\*
- 13 An Amca Noval Franca GE149 galvanized single  
 axle trailer with cover, 2.27m long x 1.37m wide
- 14 Five Range Rover Supercharged alloy wheels - four  
 with Continental Cross contact 255/55 R20 11 DW  
 all season tyres - tyre thread depth five mm each  
 (slightly used) and a further alloy wheel with 20"  
 Pirelli Scorpion Verde 255/55 R20 110 W all  
 season tyre - tyre thread depth 8mm (hardly  
 used), the four have the Land Rover badges
- 15 JAGUAR XF R-SPORT D 2.0 AUTOMATIC FOUR  
 DOOR SALOON - Diesel - Black - Black leather  
 interior.  
 On the instructions of: A retained client.  
 Registration No: RF16 UDY.  
 Recorded Mileage: 85,666.  
 First Registered: 15-08-2016.  
 Documents: Yes.  
 MOT: 15-08-2023.  
 Service History: Copy of online service history  
 shown in photos.  
 Number of Former Keepers: One.  
 Keys: Two.  
 Runner: Non Runner. Turns over but will not start.  
 Engine management light on.  
 Condition/Damages: Scratches to front wing, rear  
 door and rear wing on driver's side. Scratches to  
 rear door and rear wing on passenger side. Scuff  
 marks to wheels. Interior seats worn.